


Attachment 2
Magic-Force Wiring Diagram—iQ
(Sheet 1 of 1)



- NOTES:
1. MULTIPLE SU100 SENSOR WIRES ARE WIRED IN PARALLEL.
 2. WHEN POWER CLOSE IS REQUIRED, THE MONITORING INPUTS (BREAKOUT INPUT TB3 - 9 AND HOLDING BEAM INPUT TB5 - 7), MUST BE CONFIGURED WITH I/O CONFIGURATION PARAMETER.
 3. IF USING TB3 - 9 FOR POWER CLOSE MONITORING, BREAKOUT STATUS SWITCH MUST BE DISCONNECTED.